


CALIBRATOR 24

Setting: Ideally chose a flat, level boulder near the center of a chamber or a bend in a cave passage.




Place the device at an edge of the boulder and mark 2 opposite marking V's with nail varnish, on the rock.



Before starting the calibration remove all magnetic devices watches, phones, metalwork etc.

Put your DistoX2 into calibration mode.

For horizontal measurements align distoX here





Download zum 3D-Drucken



